

Product data sheet

Wind sensor



Reference number
132 WS
Wind sensor
(Spare part) for connection to converter ref.-no.: AT 04..
Use shielded cable (J-Y(St)Y 2x2x0.6mm ² is recommended) to connect the wind sensor.
Colour: black similar RAL 9005